



C & G Water Well Service

RR 4 Box 140  
Beaver, OK 73932

# Invoice

| Date      | Invoice # |
|-----------|-----------|
| 4/19/2018 | 180095    |

|  |
|--|
| Bill To  |
| Robert King<br>Rt 2 Box 107<br>Laverne, Ok 73848 |

**PAID**  
05/18/2018

*This is The well  
JUST off HWY 412  
To The North.*

*NO SWL and  
NO TD, because  
we have never pulled  
well.*

| Due Date  | Terms          |
|-----------|----------------|
| 4/19/2018 | Due on receipt |

| SWL | TOTAL DEPTH | PUMP SET | CASING DIA. |
|-----|-------------|----------|-------------|
|     |             |          | 5" PVC      |

| Quantity | Item Code              | Description  | Price Each | Amount |
|----------|------------------------|--|------------|--------|
| 1        | Service Call           | Service call drive to well 4 W and N into from Slapout. diagnose well issues. found no readings from motor, located burned wires, spliced back in and got good readings from down hole, turned on well, observed good readings and production left in service. | 180.00     | 180.00 |
| 2        | Heat Shrink Kit 10-... | Heat Shrink Kit 10-14  | 3.75       | 7.50   |
| 4        | 12 X 4 Jacketed Wire   | 12 X 4 Jacketed Wire   | 1.30       | 5.20   |
| 2        | 20 Amp T1 Screw i...   | 30 Amp T1 Screw in fuse  | 2.40       | 4.80   |

|  |           |
|--|-----------|
| <b>Payments/Credits</b>  | -\$197.50 |
| ANY BALANCE OVER 30 DAYS WILL BE ASSESSED 1.75% FINANCE CHARGE PER MONTH |           |
| <b>Total</b>   | \$197.50  |
| <b>Balance Due</b>   | \$0.00    |



C & G Water Well Service

RR 4 Box 140  
Beaver, OK 73932

# Invoice

| Date      | Invoice # |
|-----------|-----------|
| 4/14/2015 | 198       |

Bill To

Robert King  
Rt 2 Box 107  
Laverne, Ok 73848

**PAID**  
04/25/2015

Because we only  
Pulled rod + checks  
There is:  
NO Total Depth,  
NO STATIC  
water available

*This is The windmill  
IN The west Central  
PART of The property  
NEXT TO An oilfield  
Lease.*

| Due Date  | Terms          |
|-----------|----------------|
| 4/14/2015 | Due on receipt |

| SWL | TOTAL DEPTH | PUMP SET | CASING DIA. |
|-----|-------------|----------|-------------|
|     |             | 100      | 4.5         |

| Quantity | Item Code        | Description  | Price Each | Amount |
|----------|------------------|--|------------|--------|
| 2        | A Hourly service | Hourly rate..2 employees, rig and tools drive to location, N/S 158 & Hwy 412, 1n w into. pull rod and both checks, releather both checks, put into service. These checks are extremely worn and may need replace soon. The ball seats on both are worn into very deep boles. | 90.00      | 180.00 |
| 1        | Chlorination     | Required Chlorination and cleaning of down-hole equipment  | 1.50       | 1.50   |
| 4        | Leathers 1 7/8   | Leathers 1 7/8   | 5.00       | 20.00  |
| 1        | Oil              | Oil  | 5.50       | 5.50   |

|  |           |
|--|-----------|
| <b>Payments/Credits</b>  | -\$207.00 |
| ANY BALANCE OVER 30 DAYS WILL BE ASSESSED 1.75% FINANCE CHARGE PER MONTH |           |
| <b>Total</b>   | \$207.00  |
| <b>Balance Due</b>   | \$0.00    |



C & G Water Well Service

RR 4 Box 140  
Beaver, OK 73932

# Invoice

| Date     | Invoice # |
|----------|-----------|
| 8/6/2018 | 180204    |

**PAID**  
08/24/2018

*This is The well  
SW of The old  
house location*

|  |
|--|
| Bill To  |
| Robert King<br>Rt 2 Box 107<br>Laverne, Ok 73848 |

| Due Date | Terms          |
|----------|----------------|
| 8/6/2018 | Due on receipt |

| SWL | TOTAL DEPTH | PUMP SET | CASING DIA. |
|-----|-------------|----------|-------------|
| 35' | 200' ++     | 65'      | 5" steel    |

| Quantity | Item Code              | Description   | Price Each | Amount |
|----------|------------------------|---|------------|--------|
| 8        | A Hourly service       | Hourly rate..rig and tools drive to location located 1/2 N, W into from HWY 412 and NS 158. diagnose well issues, found control box and timer all shorted out. found the pump readings were way out of compliance. came back with back hoe. 8-9-18 drive to location dig out old pit, clearing 4' of back fill, to get to casing. pulled well, replaced pump, motor unit, ran back down hole, set new well pit, tied in well to line to tank, turned on system, got good readings, observed good production | 50.00      | 400.00 |
| 8        | A Hourly rate one e... | Hourly rate one employee  | 20.00      | 160.00 |
| 8        | A Hourly rate 2 Em...  | Hourly rate 2 Employees   | 40.00      | 320.00 |
| 1        | Gasslin GM 40 AV       | Gasslin GM 40 AV  | 135.00     | 135.00 |
| 1        | 1/2 Hp 230v control... | 1/2 hp, 230v control box  | 92.00      | 92.00  |
| 1        | 1/2 Hp 10 gpm 230v     | 1/2 Hp 10 gpm 230v J- Class Sandhandler MOTOR S/N: 17G14-01409C PUMP S/N: 17F142707717A   | 650.00     | 650.00 |
| 1        | Chlorination           | Required Chlorination and cleaning of down-hole equipment   | 1.50       | 1.50   |
| 1        | Electrical tape        | Tapes, Electrical, Teflon or 10 mil   | 2.50       | 2.50   |
| 1        | Heat Shrink Kit 10-... | Heat Shrink Kit 10-14   | 3.75       | 3.75   |
| 1        | male adapter 1"        | male adapter 1"   | 0.55       | 0.55   |
| 2        | 90 1"                  | 90 1"   | 1.10       | 2.20   |
| 1        | union 1"               | 1" Galv union   | 8.40       | 8.40   |
| 1        | Nipple 1 X 10"         | 1" X 10" Nipple   | 5.64       | 5.64   |
| 8        | Backhoe with opera...  | ditcher/backhoe with operator dig out old well pit, strip back along line going to tank, dig out four foot of fill from old pit floor, expose and clean out around well casing. dig out a 6' X 6' pit, set new pit tube, back fill, pack and push dirt up around stock tank.  | 85.00      | 680.00 |

**Payments/Credits**

-\$2,461.54

ANY BALANCE OVER 30 DAYS WILL BE ASSESSED 1.75% FINANCE CHARGE PER MONTH

**Total** \$2,461.54

**Balance Due** \$0.00